

50-inch LED Light Bar Upper Windshield Mounting Brackets
Jeep: 97-06 Wrangler TJ 4WD,
04-06 Wrangler Unlimited LJ 4WD

Parts:

- 1 - Driver Side Bracket
- 1 - Passenger Side Bracket
- 2 - Rubber Spacer Pads
- 8 - 5/16" x 1" Stainless Button-Head Bolts

PRE-INSTALLATION

Professional installation by a certified technician is strongly recommended.

Not responsible for altered products. No claims are made regarding any after-market devices. Any and all claims implied in this document excluded.

NOTES:

Light bar not included in kit.

REQUIRED TOOLS:

T-40 Wrench 3/16" Allen Wrench

INSTALLATION INSTRUCTIONS

STEP 1: Disconnect positive battery lead before installation.

STEP 2: Remove four factory bolts on windshield base. (T-40 Wrench)

STEP 3: Remove backing from rubber spacer and apply to inside of bracket. align bracket with mounting holes.

STEP 4: Align bracket and rubber pads with mounting holes on pillars.

STEP 5: Install included 5/16" stainless button-head bolts in factory holes, but leave loose. (3/16" Allen Wrench)

STEP 6: Repeat process on other side.

STEP 7: Install light bar in brackets using hardware included with kit.

STEP 8: Once light is installed, tighten all hardware.

STEP 9: Wire power to lights per instructions supplied with kit.

STEP 10: Reconnect positive battery lead.

POST-INSTALLATION

MAINTENANCE: Periodically check to ensure that all fasteners are properly tightened.