

**50-inch LED Light Bar Upper Windshield Mounting Brackets**  
**Jeep: 07-15 Wrangler JK 4WD,**  
**07-15 Wrangler Unlimited JK 4WD/2WD**

## Parts:

1 - Driver Side Bracket  
1 - Passenger Side Bracket  
2 - Rubber Spacer Pads  
10 - 8mm Stainless Button-Head Bolts

## PRE-INSTALLATION

**Professional installation by a certified technician is strongly recommended.**

*Not responsible for altered products. No claims are made regarding any after-market devices. Any and all claims implied in this document excluded.*

### NOTES:

Light bar not included in kit. Fits 50" light bars measuring 49.8" - 50.8" between mount points.

### REQUIRED TOOLS:

T-40 Wrench                      6mm Allen Wrench

## INSTALLATION INSTRUCTIONS

**STEP 1:** Disconnect positive battery lead before installation.

**STEP 2:** Remove five factory bolts on windshield base. (T-40 Wrench)

**STEP 3:** Remove backing from rubber spacer and apply to inside of bracket. align bracket with mounting holes.

**STEP 4:** Align bracket and rubber pads with mounting holes on pillars.

**STEP 5:** Install included 8mm stainless button-head bolts in factory holes - hand tighten. (6mm Allen Wrench)

**STEP 6:** Repeat process on other side.

**STEP 7:** Install light bar in brackets using hardware included with kit.

**STEP 8:** Once light is installed, tighten all hardware.

**STEP 9:** Wire power to lights per instructions supplied with kit.

**STEP 10:** Reconnect positive battery lead.

## POST-INSTALLATION

**MAINTENANCE:** Periodically check to ensure that all fasteners are properly tightened.